

**Stonehill Community
Walkaround
May/June 2010
Community's Responsibilities**

Building #1

762 - Flower box rotting
764 - Planters at deck need repair
770 - Siding at right side has damage

Building #2

782 - Woodpecker damage at right side of deck
784 - Wasp nest at entry way next to house number
786 - Woodpecker damage at privacy panel, birds nesting; siding at entry way warped
788 - Woodpecker damage at privacy panel; downspout separated from its hanger over garage
790 - End panel at windows deteriorating; siding at entry way warped

Building #3

Tree at rear of building needs trimming
850 - Woodpecker damage at lower window; extensive damage to privacy fence, deck
852, 856, 858 - Woodpecker damage at privacy panel
860 - Woodpecker damage at privacy fence at deck and at right side of the front of the garage; siding at entry way warped

Building #4

Utility service area needs weeding
880, 884, 890 - Woodpecker damage above garages at the right side

Building #5

Dumpster needs repair and weeding
870 - Trim at right hand garage door rotted; patio siding loose and warped
872 - Damage at privacy fence

Building #6

Behind Building #6 – Bench needs protection (paint? stain?)
North end of Building #6 – Downspout bent on ground; is there a bird's nest at the peak of this building?
830 - Woodpecker damage on trim at right side of roof; siding pulled away from soffit at entry way
834 - Hole in siding at the privacy fence
838 - Woodpecker damage on privacy fence at entry way
840 - Woodpecker damage on privacy fence at deck edge

Building #7

Dumpster needs painting; mail boxes leak
801 - Woodpecker damage on privacy panel; driveway at entry to garage needs repair

Building #7, cont.

805 - Driveway at entry to garage (damage caused by roofers, this has been reported 3 times)

807 - Woodpecker damage to right trim at garage

811 - Siding above entry way is rotting; driveway needs repair; garage side rail (right bottom) needs repair

Building #8

End of building – Trim shrubs away from brick wall; area around Spruce tree needs weeding; remove metal post at planting at Unit 863

Building #9

Dumpster needs paint repair

817 - Woodpecker damage at privacy fence

821 - Siding at corner at the right side and at upper roof line rotting

827 – Hole under entry walkway; two holes at roof line on east side peak

Building #10

Tree at south end of Building #10 is in sad shape – remove?

915 – Facie board and trim above right hand garage door is in bad shape

921 – Siding at privacy fence warped

Building #11

901 - Siding warped at entry way

905 – Privacy fence damage

907 – Siding warped at right side of garage; privacy fence damage

911 - Siding at the end of building is warped at both windows; hole in privacy fence

Building #12

887 and 887 at end, 889, 891, 893, 895, 897 - Privacy walls damage

887 – Deck support beam bowed; hole in the foundation at patio floor

889, 891 - Siding warped at entry way

893, 895 – Siding damage at roof line

Building #13

875 – Boards at window end warped; entry way damage

875, 877, 879, 881, 883 – Siding damage at roof line

881, 885 – Siding warped at entry ways

Building #14

833 – Bird's nest at corner of deck

Building #15

None found